



1. Drawing For DRAFT
2. Drawing to be read in conjunction with Veteran Tree Assessment Report dated August 2008.
3. The position of trees are illustrative only, exact positions to be checked and verified on site prior to construction.
4. Crown spreads illustrated are illustrative.
5. Trees are living organisms that change over time, the condition of all trees illustrated herein, are to be checked and verified by a qualified arboriculturalist or tree surgeon should works commence 12 months after the time of this survey.
6. Please note that no works should be undertaken to any trees illustrated herein without first obtaining the proper authorisation to do so.



Lindhurst, Mansfield
VETERAN TREE SURVEY PLAN
Figure 6J.1

NTS @ A3
 January 2010